



## R44 RAVEN II



### General Information

**YOM:** 2008

**TSN:** 1867 Hrs

**Engine:** LYCOMING IO-540-AE1A5

**Location:** France

**Next Major Inspection :** 2200Hrs / 12 years Inspection (May 2020)

**Important notice :** MRB replacement proceeded in January 2020  
(TSN : 40 Hrs)

*ROTOR TEAM - Helicopters Services*

*Aéroport Annecy – 74370 METZ-TESSY*

*SIRET: 53008698200010 N° TVA Intracommunautaire: FR 84530086982*

*Email : sales@rotorteam.com - Téléphone : +33 4 50 51 85 16*



## Optional Equipment Installed

- Bubble windows
- 9 Holes Console

## Radio Com / Nav & Avionics

- COM KY196A
- GPS/NAV/COM GNS430
- XPDR GTX 330
- ELT KANNAD INTEGRA AF406

## Additional Information

External Paint : Grey  
Interior : Leather Seats

## Price : On Request

*Aircraft sold "As Is" before 2200Hrs/12Y Inspection*

*Aircraft availability subject to prior sale.  
Components remaining times, configuration and equipment subject to buyer's verification prior to purchase.*

**ROTOR TEAM - Helicopters Services**

**Aéroport Annecy – 74370 METZ-TESSY**

**SIRET: 53008698200010 N° TVA Intracommunautaire: FR 84530086982**

**Email : sales@rotorteam.com - Téléphone : +33 4 50 51 85 16**



**ROTOR TEAM - Helicopters Services**

Aéroport Annecy – 74370 METZ-TESSY

SIRET: 53008698200010 N° TVA Intracommunautaire: FR 84530086982

Email : [sales@rotorteam.com](mailto:sales@rotorteam.com) - Téléphone : +33 4 50 51 85 16





**ROTOR TEAM - Helicopters Services**

Aéroport Annecy – 74370 METZ-TESSY

SIRET: 53008698200010 N° TVA Intracommunautaire: FR 84530086982

Email : [sales@rotorteam.com](mailto:sales@rotorteam.com) - Téléphone : +33 4 50 51 85 16



**ROTOR TEAM - Helicopters Services**

Aéroport Annecy – 74370 METZ-TESSY

SIRET: 53008698200010 N° TVA Intracommunautaire: FR 84530086982

Email : [sales@rotorteam.com](mailto:sales@rotorteam.com) - Téléphone : +33 4 50 51 85 16